Quality in the healthcare environment



# Safety Information Message

Reference: SIM2501 Issued: 27 January 2025 Review Date: 27 January 2026

Product Safety Report: MK Electric MK Essentials Electrical Three

Pin Sockets with Switches: risk of fire

## **Summary**

The UK Government's Office for Product Safety & Standards (OPSS) has produced a Product Safety Report for MK Electric MK Essentials Electrical Three Pin Sockets with Switches. Affected sockets present a high risk of fire and do not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs and Sockets (Safety) Regulations 1994. The products have been withdrawn from the market

### **Action**

- 1. Direct this notice to all appropriate managers, staff and users
- 2. Refer to the OPSS Product Safety Report on the MK Electric MK Essentials Electrical Three Pin Sockets with Switches <a href="here">here</a> and, if applicable, follow the required action

# **Equipment details**

Manufacturer name:	MK Electric MK Essentials	
Device name:	Electrical Three Pin Sockets with Switches	
Product names:	13A 2G SP Switched Socket model	
	13A 2G DP Switched Socket model	
	13A 2G SP Switched Socket with Neon model	
	13A 2G DP SWITCHSOCKET WITH USB PORT	
Sales period:	2018 to 3rd July 2024	
Affected models and barcodes	Refer to the OPSS Product Safety Report <a href="here">here</a> or the <a href="here">Appendix</a> at the end of this Safety Information message	









Sample images sourced from Office of Product Safety and Standards (OPSS) product safety report (2411-0130)

FAC406-275, v8 Page **1** of **5** 

Reference: SIM2501 Issued: 27 January 2025 Review Date: 27 January 2026

# **Background Information**

OPSS help manage consumer product safety incidents and provide information on products that present a serious risk to health and safety.

This OPSS Product Safety Report identifies the MK Electric MK Essentials Electrical Three Pin Sockets with Switches as presenting, "a high risk of fire as it has been identified that when the switch on the socket is being switched on, switched off, or whilst it is under load, there is a possibility for an arc flash to occur. This could cause the socket and surrounding materials to ignite, causing a fire. The affected sockets do not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs and Sockets (Safety) Regulations 1994."

The products have been withdrawn from the market.

# Suggested onward distribution (may not include all affected departments)

#### **Healthcare Facilities**

General Dental Practitioners General Medical Practitioners Health Centres Hospices

## **Corporate and Support**

Ambulance Services Health & Safety

Medical Physics Risk Management

#### Hard FM

Authorised Persons (LV)
Capital Planning & Design
Fire Safety Advisors
PFI / PPP staff

#### **Local Authority**

Care Homes
Education Property Services
Facilities Management
Health, safety and wellbeing
Housing and technical serv
Property Repairs

# **Information about IRIC**

Incident Reporting & Investigation Centre (IRIC), Facilities Division, NHSScotland Assure NHS National Services Scotland, Tel: 0131 275 7575, email: <a href="mailto:nss.iric@nhs.scot">nss.iric@nhs.scot</a>

**Accessibility**: Please contact us using the above details if you are blind or have a sight impairment and would like to request this alert in a more suitable format.

**IRIC remit**: general information about adverse incidents, safety alerts and IRIC's role can be found in <u>CEL 43 (2009)</u>, Safety of Health, Social Care, Estates and Facilities Equipment: NHS Board and Local Authority Responsibilities, issued 30 October 2009.

### To find safety alerts: scan the QR code or <u>click</u> this link to visit our website



To report an incident: scan the QR code or <u>click</u> this link to visit our website



NHS National Services Scotland is the common name for the Common Services Agency for the Scotlish Health Service <a href="https://www.nss.nhs.scot/">https://www.nss.nhs.scot/</a>

FAC406-275, v8 Page 2 of 5

Reference: SIM2501



Office for Product Safety & Standards

# **Product Safety Report**

Switches	MK Essentials Electrical Three Pin Sockets with	
Aspect De		
100	Details	
Images		
PSD Number	411-0130	
Product Type	daptors, Plugs and Sockets - 3 Pin Sockets with Switches	
Product Sa Identifiers Pl	Brand: MK Electric Sales period of affected products: 2018 to 3 <sup>rd</sup> July 2024 Please access Annex A on page 2 for details on the affected models and barcodes. Please access Annex B on page 3 for a list of product names.	
Product Description	arious models of white 3-pin wall sockets with switches.	
Country of Origin	China	
Counterfeit No	lo	
Risk Level Hi	ligh	
Risk Type Fi	ire	
Risk Description	The product presents a high risk of fire as it has been identified that when the switch on the socket is being switched on, switched off, or whilst it is under load, there is a possibility for an arc flash to occur. This could cause the socket and surrounding materials to ignite, causing a fire.  The affected sockets do not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs and Sockets (Safety) Regulations 1994.	
Corrective Measures	he products have been withdrawn from the market.	
Online Marketplace	I/A	
Notifier Lo	ocal Authority Trading Standards	

Issued: 27 January 2025

FAC406-275, v8 Page **3** of **5** 

# **Appendix**

Reference: SIM2501

# Affected models and barcodes

MV2747WHI         5017490941725         5017490949721           MV2647WHI         5017490941749         5017490949745           MV2747DPWHI         5017490941763         5017490949769           MV2647DPWHI         5017490941787         5017490949783           MV24344WHI         5017490941800         5017490949806           MV24345WHI         5017490941909         5017490949905           MV2747MBK         5017490963369         5017490971753           MV2647MBK         5017490963383         5017490971777           MV2747DPMBK         5017490963406         5017490971814           MV2647DPMBK         5017490963420         5017490971838           MV24344MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2747DPTTA         5017490966582         5017490974952           MV2647DPTTA         5017490966628         5017490974976           MV24344TTA         5017490966629         5017490975010           MV24345TTA         5017490966704         5017490973870           MV2747CHA         5017490965509         5017490973894           MV2747DPCHA         5017490965523         5017490973917           MV2647DPCHA         5017490965561	SKU/Model	Unit barcode	Pack barcode
MV2747DPWHI         5017490941763         5017490949769           MV2647DPWHI         5017490941787         5017490949783           MV24344WHI         5017490941800         5017490949806           MV24345WHI         5017490963369         50174909949905           MV2747MBK         5017490963369         5017490971773           MV2647MBK         5017490963383         5017490971777           MV2647DPMBK         5017490963406         5017490971814           MV2647DPMBK         5017490963420         5017490971818           MV24344MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966568         5017490974952           MV2747DPTTA         5017490966582         5017490974976           MV2647DPTTA         5017490966629         5017490975010           MV24344TTA         5017490966704         5017490975096           MV2747CHA         5017490965509         5017490973870           MV2647CHA         5017490965509         50174909739917           MV2647DPCHA         5017490965547         5017490973931	MV2747WHI	5017490941725	5017490949721
MV2647DPWHI         5017490941787         5017490949783           MV24344WHI         5017490941800         5017490949806           MV24345WHI         5017490941909         5017490949905           MV2747MBK         5017490963369         5017490971773           MV2647MBK         5017490963383         5017490971777           MV2747DPMBK         5017490963406         5017490971791           MV2647DPMBK         5017490963420         5017490971814           MV24344MBK         5017490963444         5017490971838           MV24345MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966582         5017490974952           MV2747DPTTA         5017490966605         55017490974976           MV2647DPTTA         5017490966605         55017490974990           MV24344TTA         5017490966704         5017490975010           MV24345TTA         5017490966704         5017490973870           MV2647CHA         5017490965509         5017490973894           MV2647CHA         5017490965523         5017490973917           MV2647DPCHA         5017490965547         5017490973931	MV2647WHI	5017490941749	5017490949745
MV24344WHI         5017490941800         5017490949806           MV24345WHI         5017490941909         5017490949905           MV2747MBK         5017490963369         5017490971753           MV2647MBK         5017490963383         5017490971777           MV2747DPMBK         5017490963406         5017490971791           MV2647DPMBK         5017490963420         5017490971814           MV24344MBK         5017490963444         5017490971838           MV24345MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966582         5017490974952           MV2747DPTTA         5017490966582         5017490974976           MV2647DPTTA         5017490966605         55017490974990           MV24344TTA         5017490966629         5017490975010           MV24345TTA         5017490965486         5017490973870           MV2747CHA         5017490965486         5017490973870           MV2647CHA         5017490965523         50174909739917           MV2647DPCHA         5017490965547         5017490973931	MV2747DPWHI	5017490941763	5017490949769
MV24345WHI         5017490941909         5017490949905           MV2747MBK         5017490963369         5017490971753           MV2647MBK         5017490963383         5017490971777           MV2747DPMBK         5017490963406         5017490971791           MV2647DPMBK         5017490963420         5017490971814           MV24344MBK         5017490963444         5017490971838           MV24345MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966582         5017490974976           MV2647DPTTA         501749096605         55017490974990           MV24344TTA         501749096609         5017490975010           MV24345TTA         5017490965486         5017490973870           MV2647CHA         5017490965509         5017490973894           MV2747DPCHA         5017490965523         5017490973917           MV2647DPCHA         5017490965547         5017490973931	MV2647DPWHI	5017490941787	5017490949783
MV2747MBK         5017490963369         5017490971753           MV2647MBK         5017490963383         5017490971777           MV2747DPMBK         5017490963406         5017490971791           MV2647DPMBK         5017490963420         5017490971814           MV24344MBK         5017490963444         5017490971838           MV24345MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966568         5017490974976           MV2647DPTTA         5017490966605         55017490974990           MV2647DPTTA         5017490966629         5017490975010           MV24344TTA         5017490966704         5017490975096           MV2747CHA         5017490965486         5017490973870           MV2647CHA         5017490965509         5017490973894           MV2747DPCHA         5017490965523         5017490973917           MV2647DPCHA         5017490965547         5017490973931	MV24344WHI	5017490941800	5017490949806
MV2647MBK         5017490963383         5017490971777           MV2747DPMBK         5017490963406         5017490971791           MV2647DPMBK         5017490963420         5017490971814           MV24344MBK         5017490963444         5017490971838           MV24345MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966582         5017490974952           MV2747DPTTA         5017490966582         5017490974976           MV2647DPTTA         5017490966605         55017490974990           MV24344TTA         5017490966629         5017490975010           MV24345TTA         5017490966704         5017490975096           MV2747CHA         5017490965509         5017490973870           MV2647CHA         5017490965509         5017490973917           MV2647DPCHA         5017490965547         5017490973931	MV24345WHI	5017490941909	5017490949905
MV2747DPMBK         5017490963406         5017490971791           MV2647DPMBK         5017490963420         5017490971814           MV24344MBK         5017490963444         5017490971838           MV24345MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966568         5017490974952           MV2747DPTTA         5017490966582         5017490974976           MV2647DPTTA         5017490966605         55017490974990           MV24344TTA         5017490966629         5017490975010           MV24345TTA         5017490966704         5017490975096           MV2747CHA         5017490965509         5017490973870           MV2647CHA         5017490965523         5017490973917           MV2647DPCHA         5017490965547         5017490973931	MV2747MBK	5017490963369	5017490971753
MV2647DPMBK         5017490963420         5017490971814           MV24344MBK         5017490963444         5017490971838           MV24345MBK         5017490963529         5017490971913           MV2747TTA         5017490966544         5017490974938           MV2647TTA         5017490966568         5017490974952           MV2747DPTTA         5017490966582         5017490974976           MV2647DPTTA         5017490966605         55017490974990           MV24344TTA         5017490966629         5017490975010           MV24345TTA         5017490966704         5017490975096           MV2747CHA         5017490965486         5017490973870           MV2647CHA         5017490965509         5017490973894           MV2747DPCHA         5017490965523         5017490973917           MV2647DPCHA         5017490965547         5017490973931	MV2647MBK	5017490963383	5017490971777
MV24344MBK       5017490963444       5017490971838         MV24345MBK       5017490963529       5017490971913         MV2747TTA       5017490966544       5017490974938         MV2647TTA       5017490966568       5017490974952         MV2747DPTTA       5017490966582       5017490974976         MV2647DPTTA       5017490966605       55017490974990         MV24344TTA       5017490966629       5017490975010         MV24345TTA       5017490966704       5017490975096         MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV2747DPMBK	5017490963406	5017490971791
MV24345MBK       5017490963529       5017490971913         MV2747TTA       5017490966544       5017490974938         MV2647TTA       5017490966568       5017490974952         MV2747DPTTA       5017490966582       5017490974976         MV2647DPTTA       5017490966605       55017490974990         MV24344TTA       5017490966629       5017490975010         MV24345TTA       5017490966704       5017490975096         MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV2647DPMBK	5017490963420	5017490971814
MV2747TTA50174909665445017490974938MV2647TTA50174909665685017490974952MV2747DPTTA50174909665825017490974976MV2647DPTTA501749096660555017490974990MV24344TTA50174909666295017490975010MV24345TTA50174909667045017490975096MV2747CHA50174909654865017490973870MV2647CHA50174909655095017490973894MV2747DPCHA50174909655235017490973917MV2647DPCHA50174909655475017490973931	MV24344MBK	5017490963444	5017490971838
MV2647TTA       5017490966568       5017490974952         MV2747DPTTA       5017490966582       5017490974976         MV2647DPTTA       5017490966605       55017490974990         MV24344TTA       5017490966629       5017490975010         MV24345TTA       5017490966704       5017490975096         MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV24345MBK	5017490963529	5017490971913
MV2747DPTTA       5017490966582       5017490974976         MV2647DPTTA       5017490966605       55017490974990         MV24344TTA       5017490966629       5017490975010         MV24345TTA       5017490966704       5017490975096         MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV2747TTA	5017490966544	5017490974938
MV2647DPTTA       5017490966605       55017490974990         MV24344TTA       5017490966629       5017490975010         MV24345TTA       5017490966704       5017490975096         MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV2647TTA	5017490966568	5017490974952
MV24344TTA       5017490966629       5017490975010         MV24345TTA       5017490966704       5017490975096         MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV2747DPTTA	5017490966582	5017490974976
MV24345TTA       5017490966704       5017490975096         MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV2647DPTTA	5017490966605	55017490974990
MV2747CHA       5017490965486       5017490973870         MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV24344TTA	5017490966629	5017490975010
MV2647CHA       5017490965509       5017490973894         MV2747DPCHA       5017490965523       5017490973917         MV2647DPCHA       5017490965547       5017490973931	MV24345TTA	5017490966704	5017490975096
MV2747DPCHA 5017490965523 5017490973917 MV2647DPCHA 5017490965547 5017490973931	MV2747CHA	5017490965486	5017490973870
MV2647DPCHA 5017490965547 5017490973931	MV2647CHA	5017490965509	5017490973894
	MV2747DPCHA	5017490965523	5017490973917
MV24344CHA 5017490965561 5017490973955	MV2647DPCHA	5017490965547	5017490973931
	MV24344CHA	5017490965561	5017490973955

FAC406-275, v8 Page **4** of **5** 

SKU/Model	Unit barcode	Pack barcode
MV24345CHA	5017490965646	5017490974037
MV2747CHM	5017490967602	5017490975997
MV2647CHM	5017490967626	5017490976017
MV2747DPCHM	5017490967640	5017490976031
MV2647DPCHM	5017490967664	5017490976055
MV24344CHM	5017490967688	5017490976079
MV24345CHM	5017490967763	5017490976154
MV2747PRL	5017490964427	5017490972811
MV2647PRL	5017490964441	5017490972835
MV2747DPPRL	5017490964465	5017490972859
MV2647DPPRL	5017490964489	5017490972873
MV24344PRL	5017490964502	5017490972897
MV24345PRL	5017490964588	5017490972972
MV2747WHI-	5017490006752	5017490007155

FAC406-275, v8 Page **5** of **5**